





October 28, 2019

Director, Air and Toxics Technical Enforcement Program
Office of Enforcement
Compliance and Environmental Justice
Mail Code 8ENF-AT
1595 Wynkoop Street
Denver, Colorado 80202-1129

OCT 3 1 2019

Enforcement and Compliance
Assurance Division

RE:

Annual Compliance Report, 40 CFR Subpart OOOOa Century Oil and Gas, LLC

To Whom It May Concern:

Attached please find a completed Annual Compliance Report under 40 Code of Federal Regulations (CFR) §60.5420a (b). This report covers includes the following:

- The Subpart OOOOa report template, supplied by the US Environmental Protection Agency (EPA) via its website, containing the information specified in §60.5420a (b).
 - This report is filed <u>early</u> as an initial annual report for the affected facilities to maintain the reporting schedule close the original annual deadline.
- A signed responsible official certification form.

Please contact me at (713) 882-5283 or by email at pmoffitt@centurynr.com if you have any questions or require additional information.

Sincerely,

(b) (6)

Patrick Moffitt Chief Operating Officer Century Oil and Gas, LLC

Enclosures

Responsible Official

Name: (Last) <u>Moffitt</u>	(First) Patrick		(MI) M
Title: Chief Operating Officer			
Company Representing: <u>Century O</u>	il and Gas, LLC		
Street or P.O. Box: 4808 Gibson St	reet, Suite 210		
City: <u>Houston</u> St	ate: <u>Texas</u> Z	ZIP: <u>77007</u>	_
Telephone (713) 882 - 5283 Ext	Facsimile		
Certification of Truth, Accuracy an	d Completeness (to be	signed by the respon	sible official)
I certify under penalty of law, base statements and information contai			* * * * * * * * * * * * * * * * * * * *
(b) (6) Name (signed):			
Name (typed): Patrick Moffitt		Date: 10	129/19

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report For each affected facility, an owner or operator must include the information specified in paragraphs (b)(1)(i) through (iv) of this section in all annual reports:

The asterisk (*) ne	xt to each field indicate	s that the corresponding	field is required.	SITE INFORMATION							ALTERNATIVE ADDRESS INFOR	RMATION (IF NO PHYSICAL ADDR	ESS AVAILABLE FOR SITE *)	REPORTING I	NFORMATION	PE Certification	ADDITION	IAL INFORMATION
Facility Record No (Field value will automatically generate if a valu is not entered.)	Company Name * (§60.5420a(b)(1)(i))	Facility Site Name * (§60.5420a(b)(1)(i))	US Well ID or US Well ID Associated with the Affected Facility, if applicable. * {\$60.5420a(b)(1)(i)}	The state of the s	Address 2	City *	County *	State Abbreviation	Zip Code *	Responsible Agency Facility ID (State Facility Identifier)	Description of Site Location (\$60.5420a(b)(1)(i))	Latitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (§60.5420a(b)(1)(i))	Longitude of the Site (decimal degrees to 5 decimals using the North	Beginning Date of Reporting Period.*		Please provide the file name that contains the certification signed by a qualified professional engineer for each closed vent system routing to a control device or process. * (\$60.5420a(b)(12)) Please provide only one file per record.		Enter associated file name reference,
	e.g.: ABC Company	e.g.: XYZ Compressor Station	e.g.: 12-345-67890-12	e.g.: 123 Main Street	t e.g.: Suite 100	e.g.: Brooklyn	e.g.: Kings Count	tye.g.; NY	e.g.: 11221		e.g.: 7 miles NE of the intersection of Hwy 123 and Hwy 456	e.g.: 34.12345	e.g.: -101.12345	e.g.: 01/01/2016	e.g.: 06/30/2016	e.g.: Certification.pdf or XYZCompressorStation.pdf		e.g.: addlinfo.zip or XYZCompressorStatio .pdf
	The state of the s	Bacon Creek Federal	49-005-59517	N/A	N/A	N/A	Campbell	WY	N/A		SESW S16 T45N R69W	43.87134	-105.1556	3/13/2019	9/30/201	9 N/A	N/A	N/A
	2 Century Oil & Gas, LLG	Jasper 32-4H	49-027-26943	N/A	N/A	N/A	Niobrara	WY	N/A		NENE S32 T40 R66W	43.40649	-104.80026	11/30/2018	9/30/2019	9 N/A	N/A	N/A

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report

For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each well site and the collection in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (§60.5420a(b)(1))	Date of Survey * (§60.5420a(b)(7)(i))	THE RESERVENCE OF STREET, STRE	Survey End Time * (§60.5420a(b)(7)(ii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (§60.5420a(b)(7)(iv))	The state of the s	Speed During Survey *			Type of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Number of Each Component Type for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))		Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))
	e.g.: Well Site ABC e	.g.: 8/13/17	e.g.: 10:00 am	e.g.: 1:00 pm	e.g.: John Smith	e.g.: 90°F	e.g.: Sunny, no clouds		e.g.: Company ABC optical gas imaging camera	e.g.: None	e.g.: Valve	e.g.: 3	e.g.: Valve	e.g.: 1
	1 Bacon Creek Federal 4	9/24/20	019 1:43 PM	2:09 PM	Leonard Robinson	73 F	30% Overcast	7.4 mph	FLIR GF320	None	Connector	1	N/A	N/A
	2 Jasper 32-4H	9/24/20	9:30 AM	9:49 AM	Leonard Robinson	63 F	40% Overcast	6.7 mph	FLIR GF320	None	PRD	1	N/A	N/A

									OGI	Compressor St	ation Affected Facility Only
Type of Difficult-to- Monitor Components Monitored * (\$60.5420a(b)(7)(ix))	Number of Each Difficult- to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(x))	Type of Unsafe-to-Monitor		Date of Successful Repair of Fugitive Emissions Component • (§60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (§60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (§60.5420a(b)(7)(iii))	Was a monitoring survey	If a monitoring survey was waived, the calendar months that make up the quarterly monitoring period for which the monitoring survey was waived. (§60.5420a(b)(7))
g.: Valve	eg.: 1	e.g.:Valve	e.g.:1	e.g.: 11/10/16	e.g.: Valve	e.g.: 1		e.g.: Company ABC optical gas imaging camera	e.g.: Trained thermographer; completed 40-hour course at XYZ Training Center. Has 10 years of experience with OGI surveys.	e.g.: Yes	e.g.: January; February; and March
/A	N/A	N/A	N/A	9/24/2019	N/A	N/A	N/A	N/A	Infrared Training Center ID# 83009/Since 2014	N/A	N/A
/A	N/A	N/A	N/A	Not repaired in reporting period	PRD	1	New parts needed to be or	r N/A	Infrared Training Center ID# 83009/Since 2014	N/A	N/A

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report For each well affected facility, an owner or operator must include the information specified in peragraphs (b)(2)(i) through (iii) of this section in all annual reports:

The asterisk (*) no	xt to each field indicate	is that the corresponding field is required.																
			§60.5432a Low Pressure Wells	All Well Completions		Well Affected Facilities Required to Comply with §60.5375a(a) and §60.5375a(f)												
Facility Record No (Select from dropdown list - may need to scroll up	United States Well Number* (§60.5420a(b)(1)(ii)	Records of deviations where well completion operations with hydraulic fracturing were not performed in compliance with the requirement specified in § 60.5375a. * (§60.5420a(b)(2)(ii) and §60.5420a(c)(1)(ii))	Please provide the file name that contains the Record of Determination and Supporting Inputs and Calculations * (§50.54204(c)(2)(will) and \$40.54204(c)(1)(will) Please provide only one file per record.	Well Completion ID *	Well Location * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(iii)(A)-(B)	Date of Onset of Flowback Following Hydraulic Fracturing or Refracturing (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(ii)(A)-(B)	Following Hydraulic Fracturing or Refracturing	Date of Each Attempt to Direct Flowback to a Separator * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(ii)(A)-(B)	Time of Each Attempt to Direct Flowback to a Separator * (\$60.5420a(c)(1)(iii)(A)- (B))	Date of Each Occurrence of Returning to the initial Flowback Stage * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(iii)(A)-(B)	Time of Each Occurrence of Returning to the Initial Flowback Stage * (\$60.5420a(b)(2)(i) and (\$60.5420a(c)(1)(iii)(A)-(B)	Date Well Shut In and Flowback Equipment Permanently Disconnected or the Startup of Production * (\$60.5420a(c)(1)(ii)(A)-(B))	Time Well Shut In and Flowback Equipment Permanently Disconnected or the Startup of Production * {\$60.5420a(c){1}(ii)(A)-{8}}	Duration of Flowback in Hours* (960.5420a(b)(2)(i) and 660.5420a(c)(1)(iii)(A)-(8)	Duration of Recovery in Hours (Not Required for Wells Complying with \$60.5375(f) (\$60.5420a(c)(1)(iii)(A))	Disposition of Recovery* (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iii)(A)- (8))	Duration of Combustion in Hours ** (\$60.5420s(c)(1)(ii) and \$60.5420s(c)(1)(iii)(A)- (B))	Duration of Venting in Hours* [\$60.5420a(c)(1)(iii)(A)- (B))
			e.g.: lowpressure.pdf or XYZCompressorStation.pdf	e.g.: Completion ABC	e.g.: 34.12345 latitude, -101.12345 longitude	e.g.: 10/16/16	eg:10am.	eg::10/16/16	eg:10 s.m.	eg:10/16/16	eg: 10am.	eg:10/16/16	eg.:10am	e.g.:5	eg.:5	e.g.: Used as onsite fuel	eg:5	eg.:5
	1 49-005-59517	N/A	N/A	BeconCreek001	(b) (9)	3/4/2019	9 a.m.	3/13/201	96 p.m.	N/A	N/A	3/13/2019	9 6 p.m.	131	N/A	N/A	13	1 N/A

			Exceptions U	nder §60.5375a(a)(3) - Tech	nically infeesible to Route to the Gas Flow Line or Col	llection System, Re-inject in	to a Well, Use as an Onsite Fuel S	ource, or Use for Another Use	ful Purpose Served By a Purcha	sed Fuel or Raw Material						Well Affected Facilitie	es Meeting the Criteria of §60.53
Reason for Venting in lieu of Capture or Combustion * (\$60.5420e(b)(2)(i) and \$60.5420e(c)(1)(III)(A)-(B))	Well Location * (\$60.5420a(b)(2)(f) and \$60.5420a(c)(1)(fv))	Specific Exception Claimed (§60.5420u(b)(2)(i) and §60.5420a(c)(1)(v))	Starting Date for the Period the Well Operated Under the Exception * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(v))	Ending Date for the Period the Well Operated Under the Exception * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iv))	Why the Well Meets the Claimed Exception * (560.5420a(c)(2)(i) and 560.5420a(c)(1)(iv))	Name of Nearest Gathering Line * (\$60.5420a(b)(2)() and \$60.5420a(c)(1)(iii)(A)-(8))	Location of Nearest Gathering Line * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(iii)(A)-(8))	Technical Considerations Preventing Bouting to this Line (\$60.5420e(b)(2)(i) and \$60.5420e(c)(1)(iii)(A)-(B))	Capture, Reinjection, and Reuse Technologies Considered * (\$60.5420a(c)(2)(i) and \$60.5420a(c)(1)(iii)(A)-(B))	Aspects of Gas or Equipment Preventing Use of Recovered Gas as a Fuel Onsite * [\$60.5420a(c)(1)(ii)(A)-(B))	Gas for Other Useful Purpose (660 5420 about 1200)	Additional Reasons for Technical Infeasibility (§60.5420a(b)(2)(i) and §60.5420a(d)(1)(iii)(A)-(B))	Well Location* ((60.5420a(b)(2)(i) and (60.5420a(c)(1)(iii)(A) and (C))	Date of Onset of Flowback Following Hydraulic Fracturing or Refracturing (\$60.5420e(b)(2)(i) and \$60.5420e(c)(1)(iii)(A) and (C))	Time of Onset of Flowback Following Hydraulic Fracturing or Refracturing (§60.5420w(b)(2)(i) and §60.5420w(c)(1)(iii)(A) and (C)	Date Well Shut in and Flowback Equipment Permanently Disconnected or the Startup of Production * (560.5420a)(2)(3) and 560.5420a)(c)(1)(ii)(A) and (C)	Time Well Shut In and Flowback Equipment Permanently Disconnected or the Startup of Production * (\$60.5420(b)(2)() and ()) \$60.5420a(c)(1)(III)(A) and (C))
unit was available at the time of completion.	e.g.: 34.12345 latitude, -101.12345 long/tude N/A	under 60.55/5a(a)(5)	e.g.: 10/16/2016 N/A	e.g.: 10/18/2016	e.g.: As further described in this report, technical issues prevented the use of the gas for useful purposes. N/A	e.g.: ABC Line	e.g.: 100 miles away at 34.12345 latitude, -101.12345 longitude N/A	e.g.: right of use	e.g.: on-site generators	e.g.: gas quality	e.g. gas quality	e.g. well damage or dean-up N/A	-101.12545 longitude	e.g.: 10/16/16 N/A			e.g.: 10 a.m.

175a(a)(1)(III)(A) - Not Hyd	raulically Fractured/Re	rfractured with Liquids or	Do Not Generate Condensate, Intermed	late Hydrocarbon Liquids, o	or Produced Water (No Lic	guid Collection System or S	Seperator Onsite			Well Affected Facilities Required to Comply with Both \$60.5975a(a)(1) and (3) Using a Digital Photo in lieu of Records Required by \$60.5420a(c)(1)(i) through (iv)		s Meeting the Criterie of \$60.5375e(g) -	:300 scf of Gas per Stock Tank Barrel of Oil Produced
Duration of Flowback in Hours.* (§60.5420a(b)(2)(i) and §60.5420a(c)(3)(iii)(A) and (C)	Duration of Combustion in Hours * (\$60.5420a(c)(1)(iii)(A) and {C}	Duration of Venting in Hours * (§60.5420e(b)(2)(i) and §60.5420e(c)(1)(iii)(A) and (C))	Reason for Venting in lieu of Capture or Combustion *	Does well still meet the conditions of 960.5373a(1)(W)(A)? * (§60.5420a(b)(2)(r) and §60.5420a(c)(1)(W)(C)(2))	If applicable Date Well Completion Operation Stopped * ([560.5420a(b)(2)0) and 560.5420a(c)(1)(iii)(C)(7))	If applicable: Time Well Completion Operation Stopped* ([560.5420a(b)(2)(i) and 560.5420a(c)(1)(iii)(C)(7))	If applicable: Date Separator Installed ((§60.5420a(b)(2)() and §60.5420a(c)(1)(iii)(C)(2)	If applicable: Time Separator Installed * ((§60.5420(b)(2)(i) and §60.5420(c)(1)(ii)(C)(2))	Are there liquids collection at the well site? Based on information and belief formed after reasonable inquire, the statements and information in the document are true, accurate, and complete. * ((\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(iii)(C)(i))	Please provide the file name that contains the Digital Photograph with Date Taken and Latitude and Longitude Imbedded (or with Visible GPS), Showing Required Equipment (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(v)) Please provide only one file per record.	Well Location* (960.5420a(b)(2)(i) and 560.5420a(c)(1)(vi)(8))	Please provide the file name that contains the Record of Analysis Performed to Claim Well Meets 562.5375eig), including GOR Values for Established Lesses and Data from Wells in the Same Basin and Field * (\$60.5420a(c)(3)(4) and \$60.5420a(c)(3)(4)(A). Please provide only one file per record.	Does the well meet the requirements of \$60.5375a(g)? Based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete. ((\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(n)(C))
eg:5	e.g.: 5	eg:5	e.g. No onsite storage or combustion unit was available at the time of completion.	e.g.: Yes	e.g.: 10/16/16	e.g.: 10 a.m.	eg::10/15/16	eg:10a.m.	e.g.: No	e.g.: completion1.pdf or XYZCompressorStation.pdf	e.g.: 34.12345 latitude, -101.12345 longitude	e.g.: GORcaics.pdf or XYZCompressorStation.pdf	e.g.: Yes
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A